Michael Anderson
Fire Chief

WEST TRENTON VOLUNTEER FIRE COMPANY NO.1, INC.
OFFICE OF THE FIRE CHIEF

40 West Upper Ferry Road Ewing, New Jersey, 08628 - (609) 883-0325 Ext. 221 - Email: chief@wtvfc.org

September 18, 2025

Re: Cellco Partnership d/b/a Verizon Wireless (TRE Sanhican)
802 River Road Ewing, N.J. 08628
Blk: 419 - Lot: 29

To: To whom it may concern,

I do have concerns ___X___ Please see attached sheet(s) ____X____

If you have any questions or concerns, please feel free to contact me.

Respectfully submitted,

Michael Anderson

Michael Anderson

Fire Chief (West Trenton section of Ewing Township)
West Trenton Vol. Fire Co. No.1, Inc

Michael Anderson
Fire Chief

WEST TRENTON VOLUNTEER FIRE COMPANY NO.1, INC.
OFFICE OF THE FIRE CHIEF

40 West Upper Ferry Road Ewing, New Jersey, 08628 - (609) 883-0325 Ext. 221 - Email: chief@wtvfc.org

Re: Cellco Partnership d/b/a Verizon Wireless (TRE Sanhican)
802 River Road Ewing, N.J. 08628
Blk: 419 - Lot: 29

I have completed the Site Plan Review of the proposed Cell Tower. I have listed the following concerns.

1. The location of the cell tower is a concern with access for larger apparatus. I have included our larger aerial apparatus turning radius spec sheet which spells out distance for emergency access during an emergency.

2. Limit parking around the fenced compound and access roadways so emergency vehicles can access the area.

3. Site plans indicating a security fence around the compound. Access into the fenced area to deenergize any equipment that could catch fire. Supplying keys to all areas for emergency access during an incident. Recommend installing a Knox Box in a location to be selected by Fire Chief or Ewing Fire Marshall's Office.

4. Site plans do not show the locations of the emergency shut offs for various equipment. I would like to identify the location as it helps with emergency response and incident mitigation. Proper labeling of disconnects and a site plan indicating what switch disconnects what equipment.

5. Recommend keeping trees and bushes far enough away from the fenced compound to prevent any ground wildfire from spreading.

6. Recommend assuring all overhead wiring is high enough to accommodate aerial apparatus access.